

10-001 (August 13, 2010)
SRS Indicator Is On With DTC 32-10
Applies To: 2006-09 Civic 2-Door – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-001.PDF>

10-002 (February 23, 2010)
Photos For Warranty Paint Repair Claims
Applies To: ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-002.PDF>

10-003 (January 16, 2010)
Fuel Fill Door Rubs Against the Quarter Panel Cladding
2009 Element – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-003.PDF>

10-004 (July 27, 2010)
Moonroof Does Not Open
Applies To: 2009-11 Pilot – See VEHICLES AFFECTED
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-004.PDF>

10-005 (January 22, 2010)
Left Third Row Seat-Back Cover Is Broken or Loose
Applies To: 2009 Pilot – ALL
2010 Pilot 2WD – From VIN 5FN3F3...AB000001 thru 5FN3F3...AB014210
2010 Pilot 4WD – From VIN 5FN3F4...AB000001 thru 5FN3F4...AB024655
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-005.PDF>

10-006 (January 29, 2010)
MIL Comes On With DTC P0171
Applies To: 2005-06 Odyssey EX-L/EX-L Touring with J35A7 (VCM) engine – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-006.PDF>

10-007 (July 2, 2010)
MIL Comes On With DTC P0300 and One or More of DTCs P0301 Thru P0306
Applies To: 2006-07 Accord Hybrid – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-007.PDF>

10-008 (April 30, 2010)
Safety Recall: Power Window Master Switch May Not Work
Applies To: 2007-08 Fit – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-008.PDF>

10-009 (March 1, 2010)
2011 Pilot: PDI and New Model Information
Applies To: 2011 Pilot – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-009.PDF>

10-010 (March 12, 2010)
2007-08 Fit: MIL Comes On with DTC P0128
Applies To: 2007-08 Fit - ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-010.PDF>

10-011 (March 5, 2010)
Service Manual Update: Power Window Goes Up and Reverses On Its Own, Is Slow to Open and Close, or Squeals, Creaks, Clunks, or Clicks
Applies To: 2003-10 Accord - ALL
2006-10 Civic - ALL
2007-10 Civic Hybrid - ALL
2007-10 CR-V - ALL
2003-10 Element - ALL
2009-10 Fit - ALL
2010 Insight - ALL
2005-10 Odyssey - ALL
2009-10 Pilot - ALL
2006-10 Ridgeline - ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-011.PDF>

10-012 (March 17, 2010)
Safety Recall: Blower Motor 2P Connector May Be Damaged
Applies To: 2006-07 Ridgeline - ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-012.PDF>

10-013 (March 12, 2010)
Rear Suspension Crunches or Squeaks Over Large Bumps
Applies To: 2009 Pilot 2WD - From VIN 5FNYF38..9B000001 thru 5FNYF38..9B028116
2009 Pilot 4WD - From VIN 5FNYF48..9B000001 thru 5FNYF48..9B055709
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-013.PDF>

10-014 (April 27, 2010)
Product Improvement Campaign: Power Tailgate May Not Stay Open
Applies To: 2005 Odyssey EX-L Touring - From VIN 5FNRL388.5B000325 thru 5FNRL388.5B133626
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-014.PDF>

10-015 (March 23, 2010)
MIL Comes On With DTC P0420
Applies To: 2007-08 Fit - ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-015.PDF>

10-016 (March 30, 2010)
A/T Gear Position Indicator Panel Squeaks
Applies To: 2008-10 Accord A/T - ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-016.PDF>

10-017 (May 14, 2010)

Safety Recall: Air In VSA Modulator-Control Unit Causes Low/Soft Brake Pedal

Applies To: 2007 Element – ALL

2008 Element 2WD – From VIN 5J6YH1...8L000001 thru 5J6YH1...8L015906

2008 Element 4WD – From VIN 5J6YH2...8L000001 thru 5J6YH2...8L018137

2007–08 Odyssey – ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-017.PDF>

10-018 (April 6, 2010)

Headliner Rattles

Applies To: 2009 Pilot EXL, EXL-R, Touring – ALL

2010 Pilot EXL, EXL-R, Touring 2WD – See VEHICLES AFFECTED

2010 Pilot EXL, EXL-R, Touring 4WD – See VEHICLES AFFECTED

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-018.PDF>

10-019 (May 7, 2010)

Popping or Clicking From the Left Rear or Right Rear Jack Point

Applies To: 2008–09 Accord Sedan – All VINs beginning with 1HG and 5KB

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-019.PDF>

10-020 (May 1, 2010)

Grinding or Thumping From the Rear Brakes

Applies To: 2007–10 CR-V – ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-020.PDF>

10-021 (May 20, 2010)

Cargo Floor Box Lid Latch Binds or Does Not Open

Applies To: 2009 Pilot – ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-021.PDF>

10-022 (May 18, 2010)

Fuel Fill Door Does Not Open

Applies To: 2009 Fit – ALL

2010 Fit – From VIN JHMGE8...AC000001 thru JHMGE8...AC013420

2010 Insight – From VIN JHMZE2...AS000001 thru JHMZE2...AS027493

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-022.PDF>

10-023 (June 2, 2010)

White Dust Comes From the HVAC Vents During A/C Use

Applies To:

2008 Accord 2-Door L4 -

From VIN 1HGCS1...8A000001 thru

1HGCS1...8A007310 thru

2008 Accord 2-Door V6 -

From VIN 1HGCS2...8A000001 thru

1HGCS2...8A004043 thru

2008 Accord 4-Door L4 -

From VIN 1HGCP2...8A000001 thru

1HGCP2...8A050358 thru

2008 Accord 4-Door V6 -
From VIN 1HGCP3...8A000001 thru
1HGCP3...8A023101 thru
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-023.PDF>

10-024 (June 11, 2010)
No XM Sound, But XM Station Information Is Displayed
All of the following models with XM radio:
2008-09 Accord
2007-09 Civic
2007-09 Civic Hybrid
2007-09 CR-V
2008-09 Element
2008-09 Odyssey
2009 Ridgeline
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-024.PDF>

10-025 (June 15, 2010)
Whistling From the Driver's or Front Passenger's Door Glass
Applies To: 2009-10 Ridgeline - ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-025.PDF>

10-026 (June 3, 2010)
Popping Noise From the Front Seat-back
Applies To: 2008-09 Accord LX, LX-P - ALL
2010 Accord LX, LX-P - From VIN 1HGCP2...AA000001 thru 1HGCP2...AA100378
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-026.PDF>

10-027 (June 2, 2010)
2011 Ridgeline: PDI Information
Applies To: 2011 Ridgeline - ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-027.PDF>

10-028 (June 17, 2010)
Rear Wheels Howl or Growl
Applies To: 2007-08 CR-V 2WD - ALL ELP and HDM produced vehicles
2009 CR-V 2WD - From VIN 5J6RE3...9L000001 thru 5J6RE3...9L021279
2009 CR-V 2WD - From VIN 3CZRE3...9G700001 thru 3CZRE3...9G705949
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-028.PDF>

10-029 (June 25, 2010)
Vehicle Pulls/Drifts Right or Pulls Right While Accelerating
Applies To: 2009 Pilot - ALL
2010 Pilot 2WD - From VIN 5FN3F3...AB000001 thru 5FN3F3...AB015647
2010 Pilot 4WD - From VIN 5FN3F4...AB000001 thru 5FN3F4...AB023050
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-029.PDF>

10-030 (July 27, 2010)

Product Update: Parasitic Current Draw From Moonroof Control Unit Can Discharge the Battery

2009 Pilot 2WD –

From VIN 5FNYP3...9B001009 thru

5FNYP3...9B028589

2009 Pilot 4WD –

From VIN 5FNYP4...9B002044 thru

5FNYP4...9B055918

2010 Pilot 2WD –

From VIN 5FNYP3...AB001826 thru

5FNYP3...AB023531

2010 Pilot 4WD –

From VIN 5FNYP4...AB001756 thru

5FNYP4...AB041284

2011 Pilot 2WD –

From VIN 5FNYP3...BB001002 thru

5FNYP3...BB008764

2011 Pilot 4WD –

From VIN 5FNYP4...BB001003 thru

5FNYP4...BB015339

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-030.PDF>

10-031 (July 9, 2010)

Moisture in the Taillight

2010 Insight – From VIN JHMZE2H..AS000001 thru JHMZE2H..AS029575

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-031.PDF>

10-032 (July 10, 2010)

Wind Whistling From Front Door Pillar

Applies To: 2010 Element – ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-032.PDF>

10-033 (August 11, 2010)

MIL Comes On With DTC P0300 Thru P0304

Applies To: 2008–10 Accord V6 with Automatic Transmission – ALL

2010 Accord Crosstour – ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-033.PDF>

10-034 (July 23, 2010)

Product Update: New Software to Help Prevent IMA Battery Deterioration

Applies To: 2006–08 Civic Hybrid – ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-034.PDF>

10-035 (July 29, 2010)

Headliner Vibrates or Rattles

Applies To: 2009–10 Ridgeline – ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-035.PDF>

10-036 (August 6, 2010)

Safety Recall: Shift Cable Socket Holder Is Incorrectly Installed

Applies To:
2010 Element LX 2WD –
From VIN 5J6YH1H3.AL004265 thru
5J6YH1H3.AL004285
2010 Element LX 4WD –
From VIN 5J6YH2H3.AL004446 thru
5J6YH2H3.AL006366
2010 Element EX 2WD –
From VIN 5J6YH1H7.AL004286 thru
5J6YH1H7.AL004324
2010 Element EX 4WD –
From VIN 5J6YH2H7.AL004686 thru
5J6YH2H7.AL007048
2010 Element SC –
From VIN 5J6YH1H9.AL004685 thru
5J6YH1H9.AL004705
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-036.PDF>

10-037 (August 10, 2010)
2011 CR-Z: PDI of the Navigation System
Applies To: 2011 CR-Z With Navigation System – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-037.PDF>

10-038 (August 5, 2010)
2011 Accord: PDI and New Model Information
Applies To: 2011 Accord – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-038.PDF>

10-039 (NOT FOUND - 14 AUG 10)

10-040 (August 7, 2010)
Front Door Armrest Leather Is Wrinkled or Bubbled
Applies To: 2007–09 CR-V EX-L – ALL
2010 CR-V EX-L 2WD – From JHLRE3H7.AC000001 to JHLRE3H7.AC001266
2010 CR-V EX-L 4WD – From JHLRE4H7.AC000001 to JHLRE4H7.AC003145
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-040.PDF>

10-041 (August 12, 2010)
2011 Honda Paint Codes
Applies To: 2011 Models – ALL
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-041.PDF>

10-042 (August 14, 2010)
Clunking, Popping, or Clicking While Turning
Applies To: 2007–09 Odyssey – ALL
2010 Odyssey – From VIN 5FNRL3...AB000001 thru 5FNRL3...AB028891
<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-042.PDF>

10-043 (NOT FOUND - 14 AUG 10)

10-044 (August 10, 2010)

2011 CR-Z: PDI Information

Applies To: 2011 CR-Z - ALL

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-044.PDF>

10-045 (August 11, 2010)

2011 Civic Sedan and Coupe: PDI Information

Applies To: 2011 Civic Sedan and Coupe - ALL except GX and Hybrid

<http://techinfo.honda.com/Rjanisis/pubs/SB/A10-045.PDF>