

## TSB Quick Look

2003 Honda Pilot EX AWD 4dr SUV (3.5L 6cyl 5A)

STRUCTURE:BODY:TAILGATE

AIR BAGS

ENGINE AND ENGINE COOLING:ENGINE

VEHICLE SPEED CONTROL

ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:BELTS AND ASSOCIATED PULLEYS

ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:BELTS AND ASSOCIATED PULLEYS

EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

EQUIPMENT:ELECTRICAL:AIR CONDITIONER

SERVICE BRAKES, HYDRAULIC:ANTILOCK:ABS WARNING LIGHT

POWER TRAIN:AUTOMATIC TRANSMISSION:COOLING UNIT AND LINES

SERVICE BRAKES, HYDRAULIC:FLUID

STRUCTURE:BODY

STRUCTURE:BODY:DOOR

POWER TRAIN:AUTOMATIC TRANSMISSION

ENGINE AND ENGINE COOLING:ENGINE

AIR BAGS:FRONTAL

STRUCTURE

EQUIPMENT:ELECTRICAL:AIR CONDITIONER

STRUCTURE:BODY

AIR BAGS:FRONTAL

ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:BELTS AND ASSOCIATED PULLEYS

EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC.

ENGINE AND ENGINE COOLING:COOLING SYSTEM

EQUIPMENT:ELECTRICAL:AIR CONDITIONER

VISIBILITY:WINDSHIELD

VEHICLE SPEED CONTROL:ACCELERATOR PEDAL

ENGINE AND ENGINE COOLING:ENGINE

POWER TRAIN:AUTOMATIC TRANSMISSION:CONTROL MODULE (TCM, PCM)

EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC.

EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL

EQUIPMENT:MECHANICAL:CARRIER/RACK

EQUIPMENT:ELECTRICAL

VISIBILITY:WINDSHIELD WIPER/WASHER

EQUIPMENT:ELECTRICAL:ANTI-THEFT DEVICES

EQUIPMENT

STEERING:HYDRAULIC POWER ASSIST SYSTEM

ENGINE AND ENGINE COOLING:ENGINE

VISIBILITY:WINDSHIELD WIPER/WASHER

EQUIPMENT

EQUIPMENT

EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

EQUIPMENT:ELECTRICAL:ANTI-THEFT DEVICES

STEERING:HYDRAULIC POWER ASSIST SYSTEM

ENGINE AND ENGINE COOLING:ENGINE

ELECTRICAL SYSTEM

ELECTRICAL SYSTEM

ELECTRICAL SYSTEM

FUEL SYSTEM, OTHER:STORAGE:FUEL GAUGE SYSTEM

AIR BAGS

OTHER

STEERING:COLUMN

STEERING

SEATS

POWER TRAIN:AUTOMATIC TRANSMISSION

STEERING

VISIBILITY:POWER WINDOW DEVICES AND CONTROLS

FUEL SYSTEM, OTHER

AIR BAGS

STEERING:HYDRAULIC POWER ASSIST SYSTEM

STRUCTURE:BODY

SERVICE BRAKES, HYDRAULIC:ANTILOCK

VISIBILITY:POWER WINDOW DEVICES AND CONTROLS

EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL

STRUCTURE:BODY

STRUCTURE:BODY:TAILGATE

AIR BAGS

SUSPENSION:FRONT

EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

FUEL SYSTEM, OTHER:STORAGE:FUEL GAUGE SYSTEM

VISIBILITY:DEFROSTER/DEFOGGER SYSTEM:WINDSHIELD:CONTROLS/WIRING

STRUCTURE:BODY

STRUCTURE:BODY

STRUCTURE:BODY

TRAILER HITCHES

VISIBILITY

VISIBILITY:REARVIEW MIRRORS/DEVICES

ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

STRUCTURE:BODY:HOOD

ENGINE AND ENGINE COOLING

FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY

OTHER

ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

ELECTRICAL SYSTEM

STRUCTURE:BODY

ENGINE AND ENGINE COOLING

STRUCTURE:BODY

OTHER

ENGINE AND ENGINE COOLING:ENGINE:GASOLINE

EQUIPMENT

Component Description:

1. STRUCTURE:BODY:TAILGATE Bulletin Number: 03060

Bulletin Date: SEP 2004

Vehicle: 2003 Honda Pilot

Summary:

SCRAPING OR POPPING WHEN OPERATING THE TAILGATE. \*TT

Component Description:

2. AIR BAGS Bulletin Number: 03066

Bulletin Date: SEP 2004

Vehicle: 2003 Honda Pilot

Summary:

SAFETY IMPROVEMENT CAMPAIGN - PILOT SRS UNIT - SERVICE BULLETIN. \*TT

Component Description:

3. ENGINE AND ENGINE COOLING:ENGINE Bulletin Number: 012704

Bulletin Date: JAN 2004

Vehicle: 2003 Honda Pilot

Summary:

REQUEST FOR VISIT. CUSTOMER COMPLAINT OF THE ENGINE STUMBLING, SHUDDERING, HESITATING, OR MOMENTARILY SURGING. MAY ALSO EXPERIENCE A CHECK ENGINE LIGHT, AND DIAGNOSTIC TROUBLE CODE (DTC) P1491 MAY BE DISPLAYED. \*TT

Component Description:

4. VEHICLE SPEED CONTROL Bulletin Number: 110303

Bulletin Date: NOV 2003

Vehicle: 2003 Honda Pilot

Summary:

REQUEST FOR PARTS. THROTTLE BODIES. COMPLAINT OF THE ACCELERATOR STICKING CLOSED OR DIFFICULT TO DEPRESS. \*TT

Component Description:

5. ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:BELTS AND ASSOCIATED PULLEYS

Bulletin Number: 03064

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

Summary:

PRODUCT UPDATE - TIMING BELT AUTO-TENSIONER SAFETY RECALL - V6 ENGINE WATER PUMP. \*TT

Component Description:

6. ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:BELTS AND ASSOCIATED PULLEYS

Bulletin Number: 03081

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

Summary:

PRODUCT UPDATE - TIMING BELT AUTO-TENSIONER. SERVICE BULLETIN. \*TT

Component Description:

7. EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

Bulletin Number: 03074

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

Summary:

## NAVIGATION SYSTEM REBOOTS WHILE USING ADVANCED CATEGORY OR DISPLAYS U. S. POST OFFICE PHONE NUMBERS INCORRECTLY. \*TT

### Component Description:

8. EQUIPMENT:ELECTRICAL:AIR CONDITIONER Bulletin Number: 1003

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

### Summary:

HEATER BLOWER MOTOR OVERHEATS OR BLOWS FUSE. VARIOUS MODELS INCLUDING THE 2004 INSIGHT AND S2000. \*TT

### Component Description:

9. SERVICE BRAKES, HYDRAULIC:ANTILOCK:ABS WARNING LIGHT Bulletin Number: 101403

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

### Summary:

INSPECTION OF ANTI-LOCK BRAKE SYSTEM (ABS) LIGHT ON. REQUEST FOR VISIT TO ALL SERVICE MANAGERS/ADVISORS. \*TT

### Component Description:

10. POWER TRAIN:AUTOMATIC TRANSMISSION:COOLING UNIT AND LINES Bulletin Number: 102703

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

### Summary:

DIGITAL PHOTOS OF LEAKING COOLER PIPE JOINT BOLT. \*TT

### Component Description:

11. SERVICE BRAKES, HYDRAULIC:FLUID Bulletin Number: 1003

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

Summary:

TESTING BRAKE FLUID FOR PETROLEUM CONTAMINATION. THIS INCLUDES 2004 INSIGHT AND S2000. \*TT

Component Description:

12. STRUCTURE:BODY Bulletin Number: 1003

Bulletin Date: OCT 2003

Vehicle: 2003 Honda Pilot

Summary:

CENTER CONSOLE LID DOESN'T LATCH OR STAY LATCHED - SERVICE TIP FROM HONDA SERVICENEWS. \*TT

Component Description:

13. STRUCTURE:BODY:DOOR Bulletin Number: 03054

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

CLICKING OR CREAKING FROM THE DOOR(S) WHILE DRIVING ON A BUMPY ROAD. \*TT

Component Description:

14. POWER TRAIN:AUTOMATIC TRANSMISSION Bulletin Number: 090103

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

AUTOMATIC TRANSMISSION (A/T) WHINE? MAKE SURE IT'S THE A/T BEFORE REPLACING IT. HONDA SERVICENEWS. \*TT

Component Description:

15. ENGINE AND ENGINE COOLING:ENGINE Bulletin Number: 092403

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

LETTER TO SERVICE MANAGER REGARDING WATER PUMP RECALL PLUS THE TIMING BELT AUTO-TENSIONER CAMPAIGN. \*TT

Component Description:

16. AIR BAGS:FRONTAL Bulletin Number: 093003

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

LETTER TO SERVICE MANAGER REGARDING SRS SAFETY IMPROVEMENT CAMPAIGN TO OPTIMIZE THE DEPLOYMENT OF THE FRONT AIRBAGS BY REPROGRAMMING THE SRS UNIT. \*TT

Component Description:

17. STRUCTURE Bulletin Number: 9112003

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

REQUEST FOR VISIT TO INSPECT THE TAILGATE SPOILER CATCHING/SNAGGING THE ROOF. \*TT

Component Description:

18. EQUIPMENT:ELECTRICAL:AIR CONDITIONER Bulletin Number: 903

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

DASH OUTLET TOO LOOSE. TECH LINE SUMMARY. \*TT

Component Description:

19. STRUCTURE:BODY Bulletin Number: 903

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

CENTER CONSOLE WON'T LATCH. TECH LINE SUMMARY. \*TT

Component Description:

20. AIR BAGS:FRONTAL Bulletin Number: 092903

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

CAMPAIGN ANNOUNCEMENT TO ALL HONDA SERVICE AND PARTS MANAGERS REGARDING SRS SAFETY IMPROVEMENT CAMPAIGN TO ENHANCE THE DEPLOYMENT OF THE FRONT AIRBAGS BY REPROGRAMMING THE SRS UNIT. \*TT

Component Description:

21. ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:BELTS AND ASSOCIATED PULLEYS Bulletin Number: 091803

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

TO ALL SERVICE & PARTS MANAGERS REGARD A PRODUCT UPDATE CAMPAIGN TO REPAIR TIMING BELT TENSIONER OIL LEAKAGE. \*TT

Component Description:

22. EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC. Bulletin Number: 090103

Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

CD CHANGER FOR PILOT LX INSTALLS IN SOME EX MODELS. HONDA SERVICENEWS. \*TT

Component Description:

23. ENGINE AND ENGINE COOLING:COOLING SYSTEM Bulletin Number: 090103



Bulletin Date: SEP 2003

Vehicle: 2003 Honda Pilot

Summary:

OUTSIDE TEMPERATURE INDICATOR LOGIC EXPLAINED. HONDA SERVICENEWS. \*TT

Component Description:

24. EQUIPMENT:ELECTRICAL:AIR CONDITIONER Bulletin Number: 03048

Bulletin Date: AUG 2003

Vehicle: 2003 Honda Pilot

Summary:

THE REAR CENTER VENTS DO NOT BLOW AIR AT ANY CLIMATE CONTROL SETTING. \*TT

Component Description:

25. VISIBILITY:WINDSHIELD Bulletin Number: 072203

Bulletin Date: JUL 2003

Vehicle: 2003 Honda Pilot

Summary:

WINDSHIELD CRACK INSPECTION. \*TT

Component Description:

26. VEHICLE SPEED CONTROL:ACCELERATOR PEDAL Bulletin Number: 060103

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

ACCELERATOR CABLE BRACKET BUZZ, RATTLE OR PINGING ON ACCELERATION. \*TT

Component Description:

27. ENGINE AND ENGINE COOLING:ENGINE Bulletin Number: 060103

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

ENGINE RUNS ROUGH FROM 40 TO 70 MPH WITH DIAGNOSTIC TROUBLE CODES P0301 THRU P0306, P1399 SET - SERVICE TIPS. \*TT

Component Description:

28. POWER TRAIN:AUTOMATIC TRANSMISSION:CONTROL MODULE (TCM, PCM) Bulletin Number: 060103

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

GRADE LOGIC CONTROL INFORMATION. \*TT

Component Description:

29. EQUIPMENT:ELECTRICAL:RADIO/TAPE DECK/CD ETC. Bulletin Number: 603

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

A CONDITION MAY EXIST WHERE THE CLOCK LOSES TIME. \*TT

Component Description:

30. EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

Bulletin Number: 603

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

A CONDITION MAY EXIST WHERE THE CUSTOMER CAN'T REMEMBER NAVIGATION SYSTEM PERSONAL IDENTIFICATION NUMBER (PIN) - INFORMATION. \*TT

Component Description:

31. ENGINE AND ENGINE COOLING:EXHAUST SYSTEM:EMISSION CONTROL Bulletin Number: 060103

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

VEHICLE'S EMISSION TYPE. \*TT

Component Description:

32. EQUIPMENT:MECHANICAL:CARRIER/RACK Bulletin Number: 060103

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

REPLACEMENT ROOF RACK INSERTS AVAILABLE. \*TT

Component Description:

33. EQUIPMENT:ELECTRICAL Bulletin Number: 060103

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

NO SOUNDS FROM FRONT DOOR SPEAKERS - COMPLAINTS. \*TT

Component Description:

34. VISIBILITY:WINDSHIELD WIPER/WASHER Bulletin Number: 060103

Bulletin Date: JUN 2003

Vehicle: 2003 Honda Pilot

Summary:

LEAKING OR DRIBBLING WINDSHIELD WASHER NOZZLES. \*TT

Component Description:

35. EQUIPMENT:ELECTRICAL:ANTI-THEFT DEVICES Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

Summary:

## FACTORY SECURITY SYSTEM DOESN'T ARM. \*TT

### Component Description:

36. EQUIPMENT Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

### Summary:

HANDS-FREE AUDIO SYSTEM MUTE LOGIC. \*TT

### Component Description:

37. STEERING:HYDRAULIC POWER ASSIST SYSTEM Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

### Summary:

INFORMATION ON WHETHER TO REPLACE THE RESERVOIR ON A NOISY POWER STEERING PUMP. \*TT

### Component Description:

38. ENGINE AND ENGINE COOLING:ENGINE Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

### Summary:

TICKING NOISE AFTER CYLINDER HEAD REPLACEMENT. \*TT

### Component Description:

39. VISIBILITY:WINDSHIELD WIPER/WASHER Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

### Summary:

TROUBLESHOOTING WINDSHIELD WASHER NOZZLE PROBLEMS. \*TT

Component Description:

40. EQUIPMENT Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

Summary:

SKIMPY HOMELINK RANGE. CHANGE BATTERIES IN REMOTE. \*TT

Component Description:

41. EQUIPMENT Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

Summary:

NEW AIR DEFLECTOR AVAILABLE. \*TT

Component Description:

42. EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

Bulletin Number: 040103

Bulletin Date: APR 2003

Vehicle: 2003 Honda Pilot

Summary:

LOOKING FOR THE NAVI SYSTEM SERIAL NUMBER IN CERTAIN VEHICLES. \*TT

Component Description:

43. EQUIPMENT:ELECTRICAL:ANTI-THEFT DEVICES Bulletin Number: 303

Bulletin Date: MAR 2003

Vehicle: 2003 Honda Pilot

Summary:

FACTORY SECURITY WON'T ARM. \*TT

Component Description:

44. STEERING:HYDRAULIC POWER ASSIST SYSTEM Bulletin Number: 303

Bulletin Date: MAR 2003

Vehicle: 2003 Honda Pilot

Summary:

POWER STEERING PUMP NOISE DUE TO OBSTRUCTED POWER STEERING RESERVOIR FILTER. \*TT

Component Description:

45. ENGINE AND ENGINE COOLING:ENGINE Bulletin Number: 303

Bulletin Date: MAR 2003

Vehicle: 2003 Honda Pilot

Summary:

TICKING NOISE AFTER CYLINDER HEAD R&R. \*TT

Component Description:

46. ELECTRICAL SYSTEM Bulletin Number: 303

Bulletin Date: MAR 2003

Vehicle: 2003 Honda Pilot

Summary:

TROUBLESHOOTING INTERMITTENT ANTI-LOCK BRAKE (ABS) OR TRACTION CONTROL SYSTEM (TCS) DIAGNOSTIC TROUBLE CODES. \*TT

Component Description:

47. ELECTRICAL SYSTEM Bulletin Number: 303

Bulletin Date: MAR 2003

Vehicle: 2003 Honda Pilot

Summary:

NAVIGATION SYSTEM SERIAL NUMBER TO OBTAIN NAVIGATION SYSTEM ANTI-THEFT CODE. \*TT

Component Description:

48. ELECTRICAL SYSTEM Bulletin Number: 303

Bulletin Date: MAR 2003

Vehicle: 2003 Honda Pilot

Summary:

HOMELINK RANGE TOO SHORT. \*TT

Component Description:

49. FUEL SYSTEM, OTHER:STORAGE:FUEL GAUGE SYSTEM Bulletin Number: 020103

Bulletin Date: FEB 2003

Vehicle: 2003 Honda Pilot

Summary:

FUEL GAUGE SENDING UNIT TEST. \*TT \*JB

Component Description:

50. AIR BAGS Bulletin Number: 020103

Bulletin Date: FEB 2003

Vehicle: 2003 Honda Pilot

Summary:

SRS INDICATOR ON WITH NO SRS DIAGNOSTIC TROUBLE CODES (DTC) SET. \*TT \*JB

Component Description:

51. OTHER Bulletin Number: 010103

Bulletin Date: JAN 2003

Vehicle: 2003 Honda Pilot

Summary:

COMPLAINTS FROM OWNERS THAT THEY CAN'T PROGRAM HOMELINK. \*TT \*JB

Component Description:

52. STEERING:COLUMN Bulletin Number: 010103

Bulletin Date: JAN 2003

Vehicle: 2003 Honda Pilot

Summary:

INSTALL THE SHIFT LOCK RELEASE SLOT COVER CORRECTLY. \*TT \*JB

Component Description:

53. STEERING Bulletin Number: 010603

Bulletin Date: JAN 2003

Vehicle: 2003 Honda Pilot

Summary:

EVALUATION OF STEERING VIBRATION. \*TT

Component Description:

54. SEATS Bulletin Number: 010603

Bulletin Date: JAN 2003

Vehicle: 2003 Honda Pilot

Summary:

ROW SEAT WILL NOT FOLD, RECLINE, TILT, OR SLIDE. \*TT

Component Description:

55. POWER TRAIN:AUTOMATIC TRANSMISSION Bulletin Number: 011303

Bulletin Date: JAN 2003

Vehicle: 2003 Honda Pilot

Summary:

INSPECTION OF AUTOMATIC TRANSMISSIONS WITH DATA TROUBLE CODE P0710  
DISPLAYED. \*TT

Component Description:

56. STEERING Bulletin Number: 011303

Bulletin Date: JAN 2003

Vehicle: 2003 Honda Pilot



**Summary:**

**FRONT DAMPER NOISE. \*TT**

**Component Description:**

**57. VISIBILITY:POWER WINDOW DEVICES AND CONTROLS Bulletin Number: 010603**

**Bulletin Date: JAN 2003**

**Vehicle: 2003 Honda Pilot**

**Summary:**

**POWER WINDOW CONTROL UNITS INTERMITTENTLY LOSING THEIR AUTO UP/DOWN FUNCTION. \*T**

**Component Description:**

**58. FUEL SYSTEM, OTHER Bulletin Number: 03001**

**Bulletin Date: JAN 2003**

**Vehicle: 2003 Honda Pilot**

**Summary:**

**MALFUNCTION INDICATOR LAMP ON WITH DIAGNOSTIC TROUBLE CODE P1457 - EVAP BYPASS SOLENOID VALVE FAILURE. \*TT**

**Component Description:**

**59. AIR BAGS Bulletin Number: 120102**

**Bulletin Date: DEC 2002**

**Vehicle: 2003 Honda Pilot**

**Summary:**

**SRS INDICATOR COMES ON AFTER BODY SHOP REPAIR. \*TT \*JB**

**Component Description:**

**60. STEERING:HYDRAULIC POWER ASSIST SYSTEM Bulletin Number: 110102**

**Bulletin Date: NOV 2002**

**Vehicle: 2003 Honda Pilot**

**Summary:**

## POWER STEERING PULLEY BELT FAILURE AFTER SERVICE BULLETIN 02-055. \*TT

### Component Description:

61. STRUCTURE:BODY Bulletin Number: 110102

Bulletin Date: NOV 2002

Vehicle: 2003 Honda Pilot

### Summary:

MISSING REAR LICENSE PLATE BOLTS. HONDA SERVICENEWS. \*TT

### Component Description:

62. SERVICE BRAKES, HYDRAULIC:ANTILOCK Bulletin Number: 110102

Bulletin Date: NOV 2002

Vehicle: 2003 Honda Pilot

### Summary:

ANTI-LOCK BRAKE SYSTEM (ABS) GRUNTS WHEN DOING A SELF-CHECK. \*TT

### Component Description:

63. VISIBILITY:POWER WINDOW DEVICES AND CONTROLS Bulletin Number: 110102

Bulletin Date: NOV 2002

Vehicle: 2003 Honda Pilot

### Summary:

SERVICE MANUAL FIX. POWER WINDOW CONTROL UNIT. HONDA SERVICENEWS. \*TT

### Component Description:

64. EQUIPMENT:OTHER:OWNERS/SERVICE/OTHER MANUAL Bulletin Number: 110102

Bulletin Date: NOV 2002

Vehicle: 2003 Honda Pilot

### Summary:

SERVICE MANUAL FIX. SERVICE MAINTENANCE SCHEDULE. HONDA SERVICENEWS. \*TT

Component Description:

65. STRUCTURE:BODY Bulletin Number: 110102

Bulletin Date: NOV 2002

Vehicle: 2003 Honda Pilot

Summary:

WHISTLING FROM DASHBOARD OR WINDSHIELD. \*TT

Component Description:

66. STRUCTURE:BODY:TAILGATE Bulletin Number: 110102

Bulletin Date: NOV 2002

Vehicle: 2003 Honda Pilot

Summary:

SCRAPING OR POPPING WHEN OPENING TAILGATE. HONDA SERVICENEWS. \*TT

Component Description:

67. AIR BAGS Bulletin Number: 110102

Bulletin Date: NOV 2002

Vehicle: 2003 Honda Pilot

Summary:

DAMAGED CABLE REEL CAN CAUSE SRS DIAGNOSTIC TROUBLE CODES (DTCS). HONDA SERVICENEWS. \*TT

Component Description:

68. SUSPENSION:FRONT Bulletin Number: 02045

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

CREAKING OR TICKING NOISE FROM THE DASHBOARD OR A FRONT STRUT. \*TT

Component Description:

69. EQUIPMENT:ELECTRICAL:NAVIGATIONAL SYSTEM(GLOBAL POSITIONING SYSTEM)

Bulletin Number: 02060

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

NAVIGATION SCREEN REVERSES COLOR. \*TT

Component Description:

70. FUEL SYSTEM, OTHER:STORAGE:FUEL GAUGE SYSTEM Bulletin Number: 100102

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

SERVICE MANUAL FIX. FUEL GAUGE SENDING UNIT TEST. HONDA SERVICENEWS. \*TT

Component Description:

71. VISIBILITY:DEFROSTER/DEFOGGER SYSTEM:WINDSHIELD:CONTROLS/WIRING

Bulletin Number: 100102

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

CALIBRATING THE OUTSIDE TEMP INDICATOR. HONDA SERVICENEWS. \*TT

Component Description:

72. STRUCTURE:BODY Bulletin Number: 1002

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

REAR LICENSE PLATE BOLTS MISSING. HONDA OCTOBER TECH LINE INFORMATION. \*TT

Component Description:

73. STRUCTURE:BODY Bulletin Number: 1002

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

RE-KEYING SIDEWINDER LOCKS. HONDA OCTOBER TECH LINE INFORMATION. \*TT

Component Description:

74. STRUCTURE:BODY Bulletin Number: 1002

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

TAILGATE SPOILER HITS ROOF. HONDA OCTOBER TECH LINE INFORMATION. \*TT

Component Description:

75. TRAILER HITCHES Bulletin Number: 1002

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

TRAILER HITCH BALL SHANK SIZES AND PART NUMBERS. HONDA OCTOBER TECH LINE INFORMATION. \*TT

Component Description:

76. VISIBILITY Bulletin Number: 100102

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

BUFFETING NOISE WITH REAR WINDOW(S) OPEN IS NORMAL. HONDA SERVICENEWS.  
\*TT

Component Description:

77. VISIBILITY:REARVIEW MIRRORS/DEVICES Bulletin Number: 100102

Bulletin Date: OCT 2002

Vehicle: 2003 Honda Pilot

Summary:

ETM FIX. AUTOMATIC DIMMING MIRROR. HONDA SERVICENEWS. \*TT

Component Description:

78. ENGINE AND ENGINE COOLING:ENGINE:GASOLINE Bulletin Number: 01009

Bulletin Date: SEP 2002

Vehicle: 2003 Honda Pilot

Summary:

SUBJECT REGARDING V6 ENGINE OIL LEAKS. \*TT

Component Description:

79. STRUCTURE:BODY:HOOD Bulletin Number: 010902

Bulletin Date: SEP 2002

Vehicle: 2003 Honda Pilot

Summary:

SUBJECT REGARDING WIND NOISE FROM HOOD AIR DEFLECTOR. \*TT

Component Description:

80. ENGINE AND ENGINE COOLING Bulletin Number: 010902

Bulletin Date: SEP 2002

Vehicle: 2003 Honda Pilot

Summary:

CUSTOMER MAY COMMENT THAT THE OUTSIDE TEMPERATURE INDICATOR DOESN'T READ ACCURATELY. \*TT

Component Description:

81. FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY Bulletin Number: 010902

Bulletin Date: SEP 2002

Vehicle: 2003 Honda Pilot

Summary:

CUSTOMER COMPLAINTS OF THUMPING FROM FUEL TANK FROM SLOSHING FUEL.. \*TT

Component Description:

82. OTHER Bulletin Number: 802

Bulletin Date: AUG 2002

Vehicle: 2003 Honda Pilot

Summary:

SUBJECT REGARDING READING READINESS CODE STATUS WITH MALFUNCTION INDICATOR LAMP. \*TT

Component Description:

83. ENGINE AND ENGINE COOLING:ENGINE:GASOLINE Bulletin Number: 010702

Bulletin Date: JUL 2002

Vehicle: 2003 Honda Pilot

Summary:

INFORMATION ON USING PGM TESTER TO NARROW DOWN MULTIPLE MISFIRE DIAGNOSTIC TROUBLE CODES. \*TT

Component Description:

84. ELECTRICAL SYSTEM Bulletin Number: 107

Bulletin Date: JUL 2002

Vehicle: 2003 Honda Pilot

Summary:

INFORMATION ON SERVICING SRS DIAGNOSTIC TROUBLE CODE 6-7 AND / OR 7-2 INTERNAL FAILURE OF SRS UNIT. \*TT

Component Description:

85. STRUCTURE:BODY Bulletin Number: 107

Bulletin Date: JUL 2002

Vehicle: 2003 Honda Pilot

Summary:

INFORMATION ON SERVICING TICKING, CLICKING NOISE AT THE DASH. \*TT

Component Description:

86. ENGINE AND ENGINE COOLING Bulletin Number: 107

Bulletin Date: JUL 2002

Vehicle: 2003 Honda Pilot

Summary:

SUBJECT REGARDING OUTSIDE AIR TEMPERATURE DISPLAY LOGIC. \*TT

Component Description:

87. STRUCTURE:BODY Bulletin Number: 107

Bulletin Date: JUL 2002

Vehicle: 2003 Honda Pilot

Summary:

SUBJECT REGARDING WIND NOISE FROM HOOD AIR DEFLECTOR. \*TT

Component Description:

88. OTHER Bulletin Number: 010702

Bulletin Date: JUL 2002

Vehicle: 2003 Honda Pilot

Summary:

SUBJECT REGARDING ANTI-THEFT RADIO SERIAL NUMBER. \*TT

Component Description:

89. ENGINE AND ENGINE COOLING:ENGINE:GASOLINE Bulletin Number: 010702

Bulletin Date: JUL 2002

Vehicle: 2003 Honda Pilot

Summary:

THIS ARTICLE APPLIES TO TORQUE SPECIFICATIONS MISSING FOR TIMING BELT TENSIONER BOLT. \*TT



**Component Description:**

**90. EQUIPMENT Bulletin Number: 602**

**Bulletin Date: JUN 2002**

**Vehicle: 2003 Honda Pilot**

**Summary:**

**SUBJECT REGARDING PGM TESTER MISFIRE COUNTER. \*TT**